

LANGSTONE



HARBOUR BOARD

LANGSTONE HARBOUR LOCAL NOTICE TO MARINERS NO. 03 OF 2021

WITHERN WRECK AND NW SINAH BUOYS RETURNED TO STATION


Mariners are advised that the Withern Wreck isolated danger buoy (unlit), in approximate position 50° 48.15'N 01° 01.824'W and

the NW Sinah starboard channel marker (flashing character green – FI G, 5s), in approximate position 50° 48.16'N, 1° 1.60'W,

have been returned to their stations.

Least depth in the vicinity of the Withern Wreck remains 2.6m below Chart Datum.

Cancel Local Notice 23 of 2019.



Owners, Agents, Charterers, Marinas, Yacht Clubs and Recreational Sailing Organisations should ensure that the contents of this Notice are made known to the Masters or persons in charge of their vessels or craft.

B Johnson
Harbour Manager

Ferry Road
Hayling Island
Hampshire
PO11 0DG
23rd March 2021